Page: 1 of: 2

Section 1. Product and Company Identification

Item Number .: s162-1

Common Name.: Carbol Fuchsin Ziehl Neelsen

Intended Use: In Vitro Diagnostic use. Laboratory Use Only

IN CASE OF EMERGENCY, CONTACT: CHEMTREC (24HR) 800-424-9300

Manufacturer.: StatLab Medical Products 2090 Commerce Drive McKinney, TX 75069 800-442-3573 Fax 972-436-1369 www.statlab.com

Section 2. Hazard Identification

227 Flammable Liquids Cat 4

- 301 Acute toxicity, oral Cat 3
- 311 Acute toxicity, dermal Cat 3
- 314 Skin corrosion/irritation Cat 1A. B. C
- 331 Acute toxicity.inhalation Cat 3
- 341 Germ cell mutagencity Cat 2
- 350 Carcinogenicity Cat 1A, 1B
- 370 Specific target organ toxicity, single exposure Cat 1



Danger

Combustible Liquid. Toxic if swallowed, inhaled and in contact with skin. Causes severe skin burns and eye damage. Suspected of causing genetic defects. May cause cancer. Causes damage to eyes. blood and CNS.

Óbtain special instructions before use. Do not handle until all precautions have been and understood. Keep away from heat/sparks/open flames/hot surfaces.-No smoking. Avoid breathing dust/fume/gas/mist/vapours/spray. Use only in a well-ventilated area. Wash hands/skin thoroughly after handling. Do not eat, drink or smoke when using this product. Wear protective gloves/protective clothing/eye protection/face protection. Keep container tightly closed, in well ventilated-area and cool. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. In case of fire: Use dry sand, dry chemical or alcohol-resistant foam to extinguish. IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician. Rinse mouth. Do not induce vomiting. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Wash skin with soap/water/shower. Call a POISON CENTER or doctor/physician if you feel unwell. Wash contaminated clothing before reuse. IF IN EYES: Rinse cautiously with water for several minutes. Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CEnter or doctor/physician. Dispose of contents/container to an approved waste disposal plant.

Hazards not otherwise covered by GHS: None

Section 3. Composition Information

Exposure Limits(A blank value indicates no information available) The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

Component	CAS#	PEL(mg/m3)	STEL(mg/m3)	CEIL(mg/m3)	Concentration Range	
Ethyl Alcohol	64-17-5		1,900.00		5-10%	
Isopropyl Alcohol	67-63-0	1,225.00	980.00		<5%	
Phenol	108-5-2		5.00		5-10%	
Basic Fuchsin	569-61-9				<5%	
Methyl Alcohol	67-56-1	325.00	260.00		<5%	

Section 4. First Aid Measures

Eye Contact: Check for and remove contact lenses. Wash with large amounts of water for 15 minutes. Seek medical attention.

Skin Contact: Remove contaminated clothing and shoes. Wash the affected area with large with soap and water. Seek medical attention

Ingestion: Give two glasses of water to a conscious victim. Do not induce vomiting. Seek medical attention

Inhalation: Move person to fresh air. If neccessary give CPR; warning this could pose a risk of exposure to the rescue breather. Seek medical attention

The most important known symptoms and effects are described in section 2 and/or section 11.

Section 5. Fire Fighting Measures

Extinguishing Media .: Use Dry Chemical, Foam or Carbon Dioxide

Special Fire and Explosion Remarks ..: N/A

Section 6. Accidental Release Measures

Spill Cleanup and Disposal Special ..: Eliminate all ignition sources and pick up with absorbent material.

Spill Cleanup.: Take up spills with absorbant material and containerize for proper disposal. Use proper PPE as per section 8. Provide ventilation.

Section 7. Handling and Storage

Storage and Handling Special..: N/A

Storage and handling .: Keep container tightly closed. Store in a cool, dry area and protect from physical damage

Section 8. Exposure Controls/Personal Protection

Personal Protective Equipment ..: Safety Goggles, Gloves, vapor Respirator

This information is provided as a guide but proper PPE can only be determined by the end user and their situation.

Engineering Controls .: Provide local exhaust ventilation to keep the airborne concentrations of vapors below their respective threshold limit values. Ensure that eyewash stations and safety showers are local to the work-station.

Section 9. Physical and Chemical Properties

Appearence Fuschia liquid	Evaporation Rate N/A	Water Soluable?: Yes
Odor: N/A	Upper Flammability Limit (%).: N/A	Volatile Percent 1.6
Odor Threshhold N/A	Lower Flammability Limit (%): N/A	Partition Coefficient n-octanol/water: N/A
pH: 0.791	Specific Gravity (@20C) 52	Auto Ignition Temp N/A
Melting Point N/A	Vapor Pressure (mm Hg): 100	Decomposition Temp: N/A
Boiling Point N/A	Vapor Density (Air=1) N/A	Viscosity N/A
Flash Point (F) TCC N/A	Relative Density N/A	

Page: 2 of: 2

Section 10. Stability and reactivity

Special Remarks on Stability ..: Stable

Special Remarks on Reactivity ..: N/A

Water Reactive.: No

Section 11. Toxological Information

Routes of Entry.: Inhalation, Ingestion, Skin absorption

Animal Toxicity .: Ethyl Alc: Acute Oral (LD50): 7060 mg/kg (Rat); Acute Dermal(LD50): 500 mg/24hr (Rabbit); Methyl Alc: Acute Oral (LD50): 5628 mg/kg (Rat); Acute Dermal (LLD50) 500mg/24hr (Rabbit); Isopropyl Alc: Acute Oral (LD50): 500 (rabbit); Phenol: Acute Oral (LD50) 317 mg/kg (Rat) Acute Dermal (LD50) 850 mg/kg (Rabbit); Basic Fuchsin: Acute Oral (LD50) 5000 mg/kg (Rabbit); Phenol: Acute Oral (LD50): 500 mg/kg (Rabbit); Basic Fuchsin: Acute Oral (LD50): 5000 mg/kg (Rabbit); Phenol: Acute Oral (LD50

Human Toxic Effects .: Target Organs: Respiratory system, skin, eyes, CNS, liver, blood and reproductive system

Potential Acute Health Effects ..: Hazardous in case of eye, skin contact, inhalation

Potential Chronic Health Effects ..: Isopropyl Alcohol: IARC Code 3; Phenol: IARC Code 3

Section 12. Ecological Information

Ecological Information .: N/A

Section 13. Disposal Considerations

Waste Disposal.: Dispose of in accordance with local, state and federal laws.

Section 14. Transport Information

DOT Identification .: Non Hazardous

Section 15. Regulatory Information
State Regulations.: New York release reporting list: Phenol

Sara Section 311 Reporting

Component	CAS#	Acu	te	Chronic	Fire	Pressure	Reactive	SARA302	SARA313	CERCLA	RCRA
Ethyl Alcohol	64-17-5	No	No	No	No	No	No	Yes	Yes	No	
Isopropyl Alcohol	67-63-0	No	No	No	No	No	No	Yes	No	No	
Phenol	108-5-2	No	No	No	No	No	Yes	Yes	Yes	No	
Basic Fuchsin	569-61-9	No	No	No	No	No	No	No	No	No	
Methyl Alcohol	67-56-1	No	No	No	No	No	No	Yes	Yes	No	

Section 16. Other Information

Review Date : 3/15/2023 Reviewed by: Admin MSDS Group Id .:

Notice: This SDS applies only to the material as packaged. If the material is altered by any means it may pose risks not mentioned here.

It is the user's responcibility to develope proper methods of handling and personal protection based on the actual conditions of use.

While this SDS is based on reliable technical data, Poly Scientific R&D Corp. assumes no responcibility for the completeness or accuracy of the information contained herein.