Page: 1 of: 2

Concentration Range

#### Section 1. Product and Company Identification

Item Number .: s121-1

Common Name .: Basic Fuchsin 0.1% Aqueous

Intended Use: In Vitro Diagnostic use. Laboratory Use Only

IN CASE OF EMERGENCY, CONTACT: CHEMTREC (24HR) 800-424-9300

Manufacturer.: Poly Scientific R&D Corp.

70 Cleveland Ave Bay Shore NY 11706

polyrnd@polyrnd.com

# Section 2. Hazard Identification

350 Carcinogenicity Cat1A, 1B



Warning

Suspected of causing cancer

Use personal protective equipmpent as requires. Obtain special instructions before use. Do not handle until all safety precautions have been read and understood.. If exposed or concerned: Get medical advice/attantion. Store locked up. Dispose of contents/container in accordance with local/regional/national/international regulations

Hazards not otherwise covered by GHS: None

#### Section 3. Composition Information

Exposure Limits(A blank value indicates no information available) The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

Component CAS# PEL(mg/m3) STEL(mg/m3) CEIL(mg/m3)

Basic Fuchsin 569-61-9 0-5%

#### Section 4. First Aid Measures

Eye Contact: Check for and remove contact lenses. Wash with large amounts of water for 15 minutes. Seek medical attention.

Skin Contact: Remove contaminated clothing and shoes. Wash the affected area with large with soap and water. Seek medical attention

Ingestion: Give two glasses of water to a conscious victim. Do not induce vomiting. Seek medical attention

Inhalation: Move person to fresh air. If neccessary give CPR; warning this could pose a risk of exposure to the rescue breather. Seek medical attention

The most important known symptoms and effects are described in section 2 and/or section 11.

#### Section 5. Fire Fighting Measures

Extinguishing Media .: Use Dry Chemical, Water Spray or Carbon Dioxide

Special Fire and Explosion Remarks ..: N/A

#### Section 6. Accidental Release Measures

Spill Cleanup and Disposal Special ..: Pick up with absorbentvermiculite

Spill Cleanup.: Take up spills with absorbant material and containerize for proper disposal. Use proper PPE as per section 8. Provide ventilation.

## Section 7. Handling and Storage

Storage and Handling Special ..: N/A

Storage and handling .: Keep container tightly closed. Store in a cool, dry area and protect from physical damage

# Section 8. Exposure Controls/Personal Protection

Personal Protective Equipment..: Safety Goggles, Gloves, Vapor Respirator

This information is provided as a guide but proper PPE can only be determined by the end user and their situation.

Engineering Controls .: Provide local exhaust ventilation to keep the airborne concentrations of vapors below their respective threshold limit values. Ensure that eyewash stations and safety showers are local to the work-station.

# Section 9. Physical and Chemical Properties

Appearence	: Fuschia liquid	Evaporation Rate N/A	Water Soluable? Yes
Odor	: N/A	Upper Flammability Limit (%).: N/A	Volatile Percent N/A
Odor Threshhold	: N/A	Lower Flammability Limit (%): N/A	Partition Coefficient n-octanol/water: N/A
pH	: N/A	Specific Gravity (@20C): N/A	Auto Ignition Temp N/A
Melting Point	: N/A	Vapor Pressure (mm Hg) N/A	Decomposition Temp: N/A
Boiling Point	: N/A	Vapor Density (Air=1) N/A	Viscosity N/A
Flash Point (F) TCC	: N/A	Relative Density N/A	

#### Section 10. Stability and reactivity

Special Remarks on Stability ..: Stable

Special Remarks on Reactivity ..: N/A

Water Reactive.: No

# Section 11. Toxological Information

Routes of Entry.: Inhalation, Skin Absorption, Ingestion

Animal Toxicity.: Acute Oral (LD50) 5gm/kg (Mouse)

Human Toxic Effects .: Target Organs: Blood, Liver

Potential Acute Health Effects..: Hazardous in case of eye,skin contact, inhalation,ingestion

Potential Chronic Health Effects ..: Mutagenic.

s121-1

SAFETY DATA SHEET

Page: 2 of: 2

Section 12. Ecological Information

Ecological Information .: N/A

# Section 13. Disposal Considerations

Waste Disposal.: Dispose of in accordance with local, state and federal laws.

Section 14. Transport Information

DOT Identification .: Non Hazardous

Section 15. Regulatory Information
State Regulations.: New York release reporting list: N/A

Sara Section 311 Reporting

Component Basic Fuchsin CERCLA RCRA CAS# Chronic Pressure Reactive SARA302 SARA313 569-61-9 No No No No No

Section 16. Other Information

Review Date : 3/14/2023 Reviewed by : Admin MSDS Group Id.:

Notice: This SDS applies only to the material as packaged. If the material is altered by any means it may pose risks not mentioned here.

It is the user's responcibility to develope proper methods of handling and personal protection based on the actual conditions of use.

While this SDS is based on reliable technical data, Poly Scientific R&D Corp. assumes no responcibility for the completeness or accuracy of the information contained herein.

Page: 1 of: 2

#### Section 1. Product and Company Identification

Item Number .: s212a-1

Common Name.: Harris Hematoxylin With Glacial Acetic Acid Intended Use: In Vitro Diagnostic use. Laboratory Use Only

IN CASE OF EMERGENCY, CONTACT: CHEMTREC (24HR) 800-424-9300

Manufacturer.: Poly Scientific R&D Corp.

70 Cleveland Ave Bay Shore NY 11706

polyrnd@polyrnd.com

# Section 2. Hazard Identification

302 Acute toxicity, oral Cat 4

314 Skin corrosion/irritation Cat 1A, B, C

335 Specific target organ toxicity, single exposure; Respiratory tract irritation Cat 3

350 Carcinogenicity Cat 1A, 1B



#### Danger

Harmful if swallowed. Causes severe skin burns and eye damage.

Do not breathe dust/fume/gas/mist/vapours/spray. Wash hands/skin thoroughly after handling. Do not eat, drink or smoke when using this product. Wear protective gloves/protective clothing/eye protection/face protection. Keep container tightly closed, in a well ventilated-area and cool. Take off contaminated clothing and wash before reuse. In case of fire: Use dry sand, dry chemical or alcohol-resistant foam to extinguish. IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell. Rinse mouth. Do not induce vomiting. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. If exposed: Call a POISON CENTER or doctor/physician. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Dispose of contents/container to an approved waste disposal plant.

Hazards not otherwise covered by GHS: None

#### Section 3. Composition Information

Exposure Limits(A blank value indicates no information available) The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

Component	CAS#	PEL(mg/m3)	STEL(mg/m3)	CEIL(mg/m3)	Concentration Range
Acetic Acid, Glacial	64-19-7	15.00	10.00		0-5%
Ethyl Alcohol	64-17-5		1,900.00		25-50%
Isopropyl Alcohol	67-63-0	1,225.00	980.00		0-5%
Hematoxylin	517-28-2				0-5%
Aluminum Potassium Sul	fi 7784-24-9				5-10%
Methyl Alcohol	67-56-1	325.00	260.00		0-5%

#### Section 4. First Aid Measures

Eye Contact: Check for and remove contact lenses. Wash with large amounts of water for 15 minutes. Seek medical attention.

Skin Contact : Remove contaminated clothing and shoes. Wash the affected area with large with soap and water. Seek medical attention

Ingestion : Give two glasses of water to a conscious victim. Do not induce vomiting. Seek medical attention

Inhalation: Move person to fresh air. If neccessary give CPR; warning this could pose a risk of exposure to the rescue breather. Seek medical attention

The most important known symptoms and effects are described in section 2 and/or section 11.

## Section 5. Fire Fighting Measures

Extinguishing Media .: Dry Chemical, Foam or Carbon Dioxide

Special Fire and Explosion Remarks ..: N/A

## Section 6. Accidental Release Measures

Spill Cleanup and Disposal Special ... Use clothing and respirator protection. Water spray to disperse vapors. Use absorbent material.

Spill Cleanup.: Take up spills with absorbant material and containerize for proper disposal. Use proper PPE as per section 8. Provide ventilation.

# Section 7. Handling and Storage

Storage and Handling Special..: N/A

Storage and handling .: Keep container tightly closed. Store in a cool, dry area and protect from physical damage

#### Section 8. Exposure Controls/Personal Protection

Personal Protective Equipment ..: Safety Glasses, Gloves, Vapor Respirator

This information is provided as a guide but proper PPE can only be determined by the end user and their situation.

Engineering Controls .: Provide local exhaust ventilation to keep the airborne concentrations of vapors below their respective threshold limit values. Ensure that eyewash stations and safety showers are local to the work-station.

# Section 9. Physical and Chemical Properties

Appearence Clear deep red liquid	Evaporation Rate N/A	Water Soluable? Yes
Odor: N/A	Upper Flammability Limit (%).: N/A	Volatile Percent N/A
Odor Threshhold: N/A	Lower Flammability Limit (%): N/A	Partition Coefficient n-octanol/water: N/A
pH: N/A	Specific Gravity (@20C) N/A	Auto Ignition Temp N/A
Melting Point: N/A	Vapor Pressure (mm Hg) N/A	Decomposition Temp N/A
Boiling Point N/A	Vapor Density (Air=1) N/A	Viscosity N/A
Flash Point (F) TCC N/A	Relative Density N/A	

# Section 10. Stability and reactivity

Special Remarks on Stability..: Stable

Special Remarks on Reactivity ..: N/A

Water Reactive.: No

Page: 2 of: 2

# Section 11. Toxological Information

Routes of Entry.: Inhalation, Skin Absorption, Ingestion

Animal Toxicity .: Ethyl Alc: Acute Oral (LD50): 7060 mg/kg (Rat); Acute Dermal(LD50): 500 mg/24hr (Rabbit); Methyl Alc: Acute Oral (LD50):5628 mg/kg (Rat); Acute Dermal (LLD50) 500mg/24hr (Rabbit); Isopropyl Alc: Acute Oral (LD50):5045 mg/kg (Rat); Acute Dermal (LD50) 500mg (Rabbit); Glacial Acetic Acid: Acute Oral (LD50): 3310 mg/kg (Rat); Acute Dermal(LD50):

Human Toxic Effects .: Target Organs: Respiratory system, skin, eyes, CNS, liver, blood and reproductive system

Potential Acute Health Effects..: Hazardous in case of inhalation, eye contact, skin contact, ingestion

Potential Chronic Health Effects ..: Isopropyl Alcohol: IARC Code 3

#### Section 12. Ecological Information

Ecological Information .: N/A

#### Section 13. Disposal Considerations

Waste Disposal.: Dispose of in accordance with local, state and federal laws.

#### Section 14. Transport Information

DOT Identification .: Non Hazardous

# Section 15. Regulatory Information

State Regulations.: New York release reporting list: Acetic Acid

#### Sara Section 311 Reporting

Component	CAS#	Acute	Chronic	Fire	Pressure	Reactive	SARA302	SARA313	CERCLA	RCRA
Acetic Acid, Glacial	64-19-7	No	No No	No No	No	No	No	Yes	No	
Ethyl Alcohol	64-17-5	No	No No	No No	No	No	Yes	Yes	No	
Isopropyl Alcohol	67-63-0	No	No No	No No	No	No	Yes	No	No	
Hematoxylin	517-28-2	No	No No	No No	No	No	No	No	No	
Aluminum Potassium Sul	f: 7784-24-9	No	No No	No No	No	No	No	No	No	
Methyl Alcohol	67-56-1	No	No No	No No	No	No	Yes	Yes	No	

Section 16. Other Information

Review Date: 3/14/2023 Reviewed by: Admin MSDS Group Id.: 82

Notice: This SDS applies only to the material as packaged. If the material is altered by any means it may pose risks not mentioned here.

It is the user's responcibility to develope proper methods of handling and personal protection based on the actual conditions of use.

While this SDS is based on reliable technical data, Poly Scientific R&D Corp. assumes no responcibility for the completeness or accuracy of the information contained herein.

#### s1867-1

SAFETY DATA SHEET

Page: 1 of: 2

#### Section 1. Product and Company Identification

Item Number .: s1867-1

Common Name.: Picric Acid Acetone 0.1%

Intended Use: In Vitro Diagnostic use. Laboratory Use Only

IN CASE OF EMERGENCY, CONTACT: CHEMTREC (24HR) 800-424-9300

Manufacturer.: Poly Scientific R&D Corp.

70 Cleveland Ave Bay Shore NY 11706

polyrnd@polyrnd.com

# Section 2. Hazard Identification

225 Flammable Liquids Cat 2

320 Serious eye damage/eye irritation Cat 2B

336 Specific target organ toxicity, single exposure; Narcotic effects Cat 3



Danger

Highly flammable liquid and vapour.

Causes eye irritation.

May cause drowsiness and dizziness

Keep away from heat/sparks/open flames/hot surfaces. No smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautinary measures against static discharge. Avoid breathing dust/fume/gas/mist/vapours/spray. Wash hands/skin thoroughly after handling. Use only in well-ventilated area. Wear protective gloves/protective clothing/eye protection/face protection. In case of fire: Use dry sand, dry chemical or alcohol- resistant foam to extinguish. IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell. Rinse mouth. Do not induce vomiting. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. IF eye irritation persists: Get medical advice/attention. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician. Store locked up in a well ventilated place and keep cool. Dispose of contents/container to an approved waste disposal plant.

Hazards not otherwise covered by GHS: None

#### Section 3. Composition Information

Exposure Limits(A blank value indicates no information available) The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

Component CAS# PEL(mg/m3) STEL(mg/m3) CEIL(mg/m3) Concentration Range

Acetone 67-64-1 1,000.00 500.00 >50%

#### Section 4. First Aid Measures

Eye Contact: Check for and remove contact lenses. Wash with large amounts of water for 15 minutes. Seek medical attention.

Skin Contact: Remove contaminated clothing and shoes. Wash the affected area with large with soap and water. Seek medical attention

Ingestion : Give two glasses of water to a conscious victim. Do not induce vomiting. Seek medical attention

Inhalation: Move person to fresh air. If necessary give CPR; warning this could pose a risk of exposure to the rescue breather. Seek medical attention.

The most important known symptoms and effects are described in section 2 and/or section 11.

# Section 5. Fire Fighting Measures

Extinguishing Media .: Carbon Dioxide or dry chemical for small. For large alcohol type or all purpose foam.

Special Fire and Explosion Remarks ..: N/A

#### Section 6. Accidental Release Measures

Spill Cleanup and Disposal Special ..: Warning! Extremely flammable! Eliminate ignition sources. Pick up spill with absorbent vermiculite

Spill Cleanup.: Take up spills with absorbant material and containerize for proper disposal. Use proper PPE as per section 8. Provide ventilation.

# Section 7. Handling and Storage

Storage and Handling Special..: N/A

Storage and handling .: Keep container tightly closed. Store in a cool, dry area and protect from physical damage

## Section 8. Exposure Controls/Personal Protection

Personal Protective Equipment ..: Safety Glasses, Gloves, Vapor Respirator

This information is provided as a guide but proper PPE can only be determined by the end user and their situation.

Engineering Controls .: Provide local exhaust ventilation to keep the airborne concentrations of vapors below their respective threshold limit values. Ensure that eyewash

stations and safety showers are local to the work-station.

# Section 9. Physical and Chemical Properties

# Section 10. Stability and reactivity

Special Remarks on Stability..: Stable

Special Remarks on Reactivity ..: N/A

Water Reactive.: No

s1867-1

SAFETY DATA SHEET

Page: 2 of: 2

# Section 11. Toxological Information

Routes of Entry.: Inhalation, Skin Absorption, Ingestion

Animal Toxicity :: Acute Oral (LD50) 975 mg/kg (Rat); Acute Dermal (LD50) 20 gm/kg (Rabbit); Acute Inhalation (LC50) 1600PPM/24hrs (Rat); Oral (TDLO) 2857 mg/kg (Man); Skin 500 mg/24hrs (mild irritation) (Rabbit); Eyes 100gm/24hrs (Moderate irritation) (Rabbit)

Human Toxic Effects .: Target Organs:Eyes, skin, respiratory system, central nervous system

Potential Acute Health Effects ..: Hazardous in case of inhalation, eye contact, skin contact, ingestion

Potential Chronic Health Effects ..: N/A

#### Section 12. Ecological Information

Ecological Information .: N/A

#### Section 13. Disposal Considerations

Waste Disposal.: Dispose of in accordance with local, state and federal laws.

#### Section 14. Transport Information

DOT Identification .: UN1090, Acetone,3,II

# Section 15. Regulatory Information

State Regulations.: New York release reporting list: Acetone

Sara Section 311 Reporting

Component CAS# Chronic Pressure Reactive SARA302 SARA313 CERCLA **RCRA** Acute Acetone 67-64-1 No No No Yes No

Section 16. Other Information

Review Date : 3/14/2023 Reviewed by : Admin MSDS Group Id .: 149

Notice: This SDS applies only to the material as packaged. If the material is altered by any means it may pose risks not mentioned here.

It is the user's responcibility to develope proper methods of handling and personal protection based on the actual conditions of use.

While this SDS is based on reliable technical data, Poly Scientific R&D Corp. assumes no responcibility for the completeness or accuracy of the information contained herein.