Page: 1 of: 2

Section 1. Product and Company Identification

Item Number .: s1910-1

Common Name .: Wheatleys Trichrome Stain

Intended Use: In Vitro Diagnostic use. Laboratory Use Only

IN CASE OF EMERGENCY, CONTACT: CHEMTREC (24HR) 800-424-9300


Manufacturer.: Poly Scientific R&D Corp.

70 Cleveland Ave Bay Shore NY 11706

polyrnd@polyrnd.com

Section 2. Hazard Identification

314 Skin corrosion/irritation Cat 1A, B, C





Danger

Causes severe skin burns and eye damage. Suspected of causing genetic defects.

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not breathe dust/fume/gas/mist/vapours/spray. Wash hands/skin thoroughly after handling. Do not eat, drink or smoke when using this product. Wear protective gloves/protective clothing/eye protection/face protection. Keep container tightly closed, locked up in well ventilated-area and cool. Take precautionary measures against static discharge. Take off contaminated clothing and wash before reuse. In case of fire: Use dry sand, dry chemical or alcohol-resistant foam to extinguish. IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell. Rinse mouth. Do not induce vomiting. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. If exposed: Call a POISON CENTER or doctor/physician. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Dispose of contents/container to an approved waste disposal plant.

Hazards not otherwise covered by GHS: None

Section 3. Composition Information

Exposure Limits(A blank value indicates no information available) The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

CAS# PEL(mg/m3) STEL(mg/m3) CEIL(mg/m3) Concentration Range Component

Acetic Acid. Glacial 64-19-7 0-5% 15 00 10.00

Fast Green FCF 2353-45-9 0-5%

Section 4. First Aid Measures

Eye Contact: Check for and remove contact lenses. Wash with large amounts of water for 15 minutes. Seek medical attention.

Skin Contact: Remove contaminated clothing and shoes. Wash the affected area with large with soap and water. Seek medical attention

Ingestion: Give two glasses of water to a conscious victim. Do not induce vomiting. Seek medical attention

Inhalation: Move person to fresh air. If neccessary give CPR; warning this could pose a risk of exposure to the rescue breather. Seek medical attention

The most important known symptoms and effects are described in section 2 and/or section 11.

Section 5. Fire Fighting Measures

Extinguishing Media .: Water, Dry Chemical Foam or CO2

Special Fire and Explosion Remarks ..: N/A

Section 6. Accidental Release Measures

Spill Cleanup and Disposal Special ..: Wear protective clothing and respirator equipment. Disperse vapors with water spray and dilute. Pick up with absorbent material Spill Cleanup.: Take up spills with absorbant material and containerize for proper disposal. Use proper PPE as per section 8. Provide ventilation.

Section 7. Handling and Storage

Storage and Handling Special ..: N/A

Storage and handling .: Keep container tightly closed. Store in a cool, dry area and protect from physical damage

Section 8. Exposure Controls/Personal Protection

Personal Protective Equipment ..: Safety Glasses, Gloves, Vapor Respirator

This information is provided as a guide but proper PPE can only be determined by the end user and their situation.

Engineering Controls: Provide local exhaust ventilation to keep the airborne concentrations of vapors below their respective threshold limit values. Ensure that eyewash stations and safety showers are local to the work-station.

Section 9. Physical and Chemical Properties

Appearence Clear purple liquid	Evaporation Rate N/A	Water Soluable?: Yes
Odor: Slight vinegar	Upper Flammability Limit (%).: N/A	Volatile Percent 100
Odor Threshhold N/A	Lower Flammability Limit (%): N/A	Partition Coefficient n-octanol/water: N/A
pH: N/A	Specific Gravity (@20C): 1.05	Auto Ignition Temp: N/A
Melting Point N/A	Vapor Pressure (mm Hg): 11	Decomposition Temp: N/A
Boiling Point N/A	Vapor Density (Air=1) 2.1	Viscosity N/A
Flash Point (F) TCC N/A	Relative Density N/A	

Section 10. Stability and reactivity

Special Remarks on Stability ..: Stable

Special Remarks on Reactivity ..: N/A

s1910-1 SAFETY DATA SHEET

Page: 2 of: 2

Section 11. Toxological Information

Routes of Entry.: Inhalation, Skin Absorption, Ingestion

Animal Toxicity.: Glacial Acetic Acid: Acute Oral (LD50): 3310 mg/kg (Rat); Acute Dermal(LD50): 1060 mg/kg (Rabbit); Fast Green: Subcutaneous (LDLO) 5925 mg/kg (Rat); Light Green S.F. Yellowish: Acute Oral (LD50) 2gm/kg (Rat) I.V. (LD50) 700 mg/kg (Mouse)

Human Toxic Effects .: Target Organs: Lungs, mucous membranes, upper respitory tract, skin,eyes,teeth

Potential Acute Health Effects ..: Hazardous in case of inhalation, eye contact, skin contact, ingestion

Potential Chronic Health Effects ..: Fast Green: IARC Code 3; Light Green SF: IARC Code 3

Section 12. Ecological Information

Ecological Information .: N/A

Section 13. Disposal Considerations

Waste Disposal.: Dispose of in accordance with local, state and federal laws.

Section 14. Transport Information

DOT Identification .: Non Hazardous

Section 15. Regulatory Information
State Regulations.: New York release reporting list: Glacial Acetic Acid

Sara Section 311 Reporting

Component	CAS#	Acu	ıte	Chronic	Fire	Pressure	Reactive	SARA302	SARA313	CERCLA	RCRA
Acetic Acid, Glacial	64-19-7	No	No	No	No	No	No	No	Yes	No	
Fast Green FCF	2353-45-9	No	No	No	No	No	No	No	No	No	

Section 16. Other Information Review Date : 3/14/2023

Reviewed by : Admin MSDS Group Id.:

Notice: This SDS applies only to the material as packaged. If the material is altered by any means it may pose risks not mentioned here.

It is the user's responcibility to develope proper methods of handling and personal protection based on the actual conditions of use.

s2030-1

SAFETY DATA SHEET

Page: 1 of: 2

Section 1. Product and Company Identification

Item Number .: s2030-1

Common Name.: Iodine Alcohol For Trichrome

Intended Use: In Vitro Diagnostic use. Laboratory Use Only

IN CASE OF EMERGENCY, CONTACT: CHEMTREC (24HR) 800-424-9300

Manufacturer.: Poly Scientific R&D Corp.

70 Cleveland Ave Bay Shore NY 11706

polyrnd@polyrnd.com

Section 2. Hazard Identification

225 Flammable Liquids Cat 2

302 Acute toxicity, oral Cat 4

318 Serious eye damage/eye irritation Cat 1

370 Specific target organ toxicity, single exposure Cat 1



Danger

Highly flammable liquid and vapour. Harmful if swallowed. Causes skin irritation. Causes serious eye damage. Causes damage to eyes, blood and CNS.

Keep away from heat/sparks/open flames/hot surfaces.-No smoking. Do not breathe dust/fume/gas/mist/vapours/spray. Wash hands/skin thoroughly after handling. Do not eat, drink or smoke when using this product. Wear protective gloves/protective clothing/eye protection/face protection. Keep container tightly closed, locked. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. IF SWALLOWED: Call a POISON CENTER or doctor/physician if you feel unwell. Rinse mouth. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. If INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Store in well-ventilated, cool area. In case of fire: Use dry sand, dry chemical or alcohol- resistant foam to extinguish. Dispose of contents/container to an approved waste disposal plant.

Hazards not otherwise covered by GHS: None

Section 3. Composition Information

Exposure Limits(A blank value indicates no information available) The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

Component	CAS#	PEL(mg/m3)	STEL(mg/m3)	CEIL(mg/m3)	Concentration Range
Ethyl Alcohol	64-17-5		1,900.00	>50%	6
Isopropyl Alcohol	67-63-0	1,225.00	980.00	0-5%	
Iodine	7553-56-2	0.10	1.00	0-5%	
Methyl Alcohol	67-56-1	325.00	260.00	0-5%	

Section 4. First Aid Measures

Eye Contact: Check for and remove contact lenses. Wash with large amounts of water for 15 minutes. Seek medical attention.

Skin Contact: Remove contaminated clothing and shoes. Wash the affected area with large with soap and water. Seek medical attention

Ingestion: Give two glasses of water to a conscious victim. Do not induce vomiting. Seek medical attention

Inhalation : Move person to fresh air. If neccessary give CPR; warning this could pose a risk of exposure to the rescue breather. Seek medical attention

The most important known symptoms and effects are described in section 2 and/or section 11.

Section 5. Fire Fighting Measures

Extinguishing Media .: Use Dry Chemical, Foam or Carbon Dioxide

Special Fire and Explosion Remarks ..: N/A

Section 6. Accidental Release Measures

Spill Cleanup and Disposal Special ..: Eliminate all ignition sources. Take up spills with absorbent material.

Spill Cleanup.: Take up spills with absorbant material and containerize for proper disposal. Use proper PPE as per section 8. Provide ventilation.

Section 7. Handling and Storage

Storage and Handling Special..: N/A

Storage and handling .: Keep container tightly closed. Store in a cool, dry area and protect from physical damage

Section 8. Exposure Controls/Personal Protection

Personal Protective Equipment ..: Safety Glasses, Gloves, Vapor Respirator

This information is provided as a guide but proper PPE can only be determined by the end user and their situation.

Engineering Controls .: Provide local exhaust ventilation to keep the airborne concentrations of vapors below their respective threshold limit values. Ensure that eyewash

stations and safety showers are local to the work-station.

Section 9. Physical and Chemical Properties

Appearence Clear dark brown liquid	Evaporation Rate N/A	Water Soluable? Yes
Odor N/A	Upper Flammability Limit (%).: N/A	Volatile Percent 100
Odor Threshhold N/A	Lower Flammability Limit (%): N/A	Partition Coefficient n-octanol/water: N/A
pH: N/A	Specific Gravity (@20C) 0.791	Auto Ignition Temp: N/A
Melting Point N/A	Vapor Pressure (mm Hg): 52	Decomposition Temp: N/A
Boiling Point: N/A	Vapor Density (Air=1) 1.6	Viscosity: N/A
Flash Point (F) TCC N/A	Relative Density N/A	

Section 10. Stability and reactivity

Special Remarks on Stability ..: Stable

Special Remarks on Reactivity ..: N/A

Page: 2 of: 2

Section 11. Toxological Information

Routes of Entry.: Inhalation, Skin Absorption, Ingestion

Animal Toxicity.: Ethyl Alcohol: Acute Oral (LD50) 7060 mg/kg (Rat) Acute Dermal 500mg/24hr (Rabbit); Methyl Alcohol: Acute Oral (LD50) 5628 mg/kg (Rat) Acute Dermal 500mg/24hr (Rabbit); Isopropyl Alcohol: Acute Oral (LD50) 5045 mg/kg (Rat) Acute Dermal 500mg/24hr (Rabbit); Iodine: Acute Oral (LD50) 14 gm/kg (Rat) Acute Oral (LD50) 10 gm/kg (Rabbit)

Human Toxic Effects .: Target Organs: N/A

Potential Acute Health Effects ..: Hazardous in case of inhalation, eye contact, skin contact, ingestion

Potential Chronic Health Effects ..: Isopropyl Alcohol: IARC Code 3

Section 12. Ecological Information

Ecological Information .: N/A

Section 13. Disposal Considerations

Waste Disposal.: Dispose of in accordance with local, state and federal laws.

Section 14. Transport Information

DOT Identification .: UN1170, Ethanol Solutions,3,III

Section 15. Regulatory Information

State Regulations.: New York release reporting list: N/A

Sara Section 311 Reporting

Component	CAS#	Acu	ıte	Chronic	Fire	Pressure	Reactive	SARA302	SARA313	CERCLA	RCRA
Ethyl Alcohol	64-17-5	No	No	No	No	No	No	Yes	Yes	No	
Isopropyl Alcohol	67-63-0	No	No	No	No	No	No	Yes	No	No	
Iodine	7553-56-2	No	No	No	No	No	No	No	No	No	
Methyl Alcohol	67-56-1	No	No	No	No	No	No	Yes	Yes	No	
Continu 1C Other Inf											

Section 16. Other Information

Review Date : 3/14/2023 Reviewed by : Admin MSDS Group Id .: 173

Notice: This SDS applies only to the material as packaged. If the material is altered by any means it may pose risks not mentioned here.

It is the user's responcibility to develope proper methods of handling and personal protection based on the actual conditions of use.

s2031-1

SAFETY DATA SHEET

Page: 1 of: 2

Section 1. Product and Company Identification

Item Number .: s2031-1

Common Name .: Acid Alcohol Trichrome Stain

Intended Use: In Vitro Diagnostic use. Laboratory Use Only

IN CASE OF EMERGENCY, CONTACT: CHEMTREC (24HR) 800-424-9300

Manufacturer.: Poly Scientific R&D Corp.

70 Cleveland Ave Bay Shore NY 11706

polyrnd@polyrnd.com

Section 2. Hazard Identification

225 Flammable Liquids Cat 2

302 Acute toxicity, oral Cat 4

370 Specific target organ toxicity, single exposure Cat 1



Danger

Highly flammable liquid and vapour.

Harmful if swallowed. Causes damage to CNS, Kidneys and Liver.

Keep away from heat/sparks/open flames/hot surfaces. - No smoking.

Use explosion-proof electrical/ventilating/lighting/equipment.

Use only non-sparking tools. Take precautionary measures against static discharge.Do not breathe dust/ fume/ gas/ mist/ vapours/ spray.

Wash hands/skin thoroughly after handling. Do not eat, drink or smoke when using this product. Wear protective gloves/ protective clothing/ eye protection/ face protection. IF SWALLOWED: Call a POISON CENTER or doctor/ physician if you feel unwell. Rinse mouth. IF ON SKIN (or hair): Remove/ Take off immediately all contaminated clothing. Rinse skin with water/ shower. IF exposed: Call a POISON CENTER or doctor/ physician.

In case of fire: Use dry sand, dry chemical or alcohol-resistant foam for

extinction. Store in a well-ventilated place tightly closed. Keep cool and locked up. Dispose of contents/ container to an approved waste disposal plant.

Hazards not otherwise covered by GHS: None

Section 3. Composition Information

Exposure Limits(A blank value indicates no information available) The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

Component	CAS#	PEL(mg/m3)	STEL(mg/m3)	CEIL(mg/m3)	Concentration Range
Ethyl Alcohol	64-17-5		1,900.00		>50%
Isopropyl Alcohol	67-63-0	1,225.00	980.00		0-5%
Methyl Alcohol	67-56-1	325.00	260.00		0-5%

Section 4. First Aid Measures

Eye Contact: Check for and remove contact lenses. Wash with large amounts of water for 15 minutes. Seek medical attention.

Skin Contact: Remove contaminated clothing and shoes. Wash the affected area with large with soap and water. Seek medical attention

Ingestion: Give two glasses of water to a conscious victim. Do not induce vomiting. Seek medical attention

Inhalation: Move person to fresh air. If neccessary give CPR; warning this could pose a risk of exposure to the rescue breather. Seek medical attention

The most important known symptoms and effects are described in section 2 and/or section 11.

Section 5. Fire Fighting Measures

Extinguishing Media .: Dry Chemical Powder, Alcohol Foam, Carbon Dioxide

Special Fire and Explosion Remarks ..: N/A

Section 6. Accidental Release Measures

Spill Cleanup and Disposal Special ..: Warning!! Flammable!! Eliminate ignition sources. Take up spills with absorbent material.

Spill Cleanup.: Take up spills with absorbant material and containerize for proper disposal. Use proper PPE as per section 8. Provide ventilation.

Section 7. Handling and Storage

Storage and Handling Special ..: Refrigerate

Storage and handling .: Keep container tightly closed. Store in a cool, dry area and protect from physical damage

Section 8. Exposure Controls/Personal Protection

Personal Protective Equipment ..: Safety Glasses, Gloves, Vapor Respirator

This information is provided as a guide but proper PPE can only be determined by the end user and their situation.

Engineering Controls .: Provide local exhaust ventilation to keep the airborne concentrations of vapors below their respective threshold limit values. Ensure that eyewash

stations and safety showers are local to the work-station.

Section 9. Physical and Chemical Properties

Appearence Colorless liquid	Evaporation Rate N/A	Water Soluable? Yes
Odor Pleasant	Upper Flammability Limit (%).: N/A	Volatile Percent: 100
Odor Threshhold N/A	Lower Flammability Limit (%): N/A	Partition Coefficient n-octanol/water: N/A
pH N/A	Specific Gravity (@20C) 0.7915	Auto Ignition Temp: N/A
Melting Point N/A	Vapor Pressure (mm Hg): 52	Decomposition Temp: N/A
Boiling Point N/A	Vapor Density (Air=1) 1.6	Viscosity N/A
Flash Point (F) TCC N/A	Relative Density N/A	

Section 10. Stability and reactivity

Special Remarks on Stability ..: Stable

Special Remarks on Reactivity ..: N/A

Page: 2 of: 2

Section 11. Toxological Information

Routes of Entry.: Inhalation, Skin absorbtion, Ingestion

Animal Toxicity .: Ethyl Alc: Acute Oral (LD50): 7060 mg/kg (Rat); Acute Dermal(LD50): 500 mg/24hr (Rabbit); Methyl Alc: Acute Oral (LD50):5628 mg/kg (Rat); Acute Dermal (LLD50) 500mg/24hr (Rabbit); Isopropyl Alc: Acute Oral (LD50):5045 mg/kg (Rat); Acute Dermal (LD50) 500mg (Rabbit);

Human Toxic Effects .: Target Organs: Respiratory system, skin, eyes, CNS, liver, blood and reproductive system

Potential Acute Health Effects ..: Hazardous in case of eye, skin contact, inhalation, ingestion

Potential Chronic Health Effects ..: Isopropyl Alcohol: IARC code 3

Section 12. Ecological Information

Ecological Information .: N/A

Section 13. Disposal Considerations

Waste Disposal.: Dispose of in accordance with local, state and federal laws.

Section 14. Transport Information

DOT Identification .: UN1170, Ethanol Solutions,3,II

Section 15. Regulatory Information
State Regulations.: New York release reporting list: N/A

Sara Section 311 Reporting

Component	CAS#	Acu	ite	Chronic	Fire	Pressure	Reactive	SARA302	SARA313	CERCLA	RCRA
Ethyl Alcohol	64-17-5	No	No	No	No	No	No	Yes	Yes	No	
Isopropyl Alcohol	67-63-0	No	No	No	No	No	No	Yes	No	No	
Methyl Alcohol	67-56-1	No	No	No	No	No	No	Yes	Yes	No	

Section 16. Other Information

Review Date : 3/14/2023 Reviewed by : Admin MSDS Group Id .:

Notice: This SDS applies only to the material as packaged. If the material is altered by any means it may pose risks not mentioned here.

It is the user's responcibility to develope proper methods of handling and personal protection based on the actual conditions of use.

s2032-1

SAFETY DATA SHEET

Page: 1 of: 2

Section 1. Product and Company Identification

Item Number .: s2032-1

Common Name.: Carbol Xylene For Intestinal Protozoa Trichrome Intended Use: In Vitro Diagnostic use. Laboratory Use Only

IN CASE OF EMERGENCY, CONTACT: CHEMTREC (24HR) 800-424-9300

Manufacturer.: Poly Scientific R&D Corp.

70 Cleveland Ave Bay Shore NY 11706

polyrnd@polyrnd.com

Section 2. Hazard Identification

226 Flammable Liquids Cat 3

- 301 Acute toxicity, oral Cat 3
- Acute toxicity, dermal Cat 3
- 314 Skin corrosion/irritation Cat 1A. B. C
- Acute toxicity inhalation Cat 3 331
- Germ cell mutagencity Cat 2
- 370 Specific target organ toxicity, single exposure Cat 1



Danger

Flammable liquid and vapour. Toxic if swallowed, inhaled and in contact with skin. Causes severe skin burns and eye damage. Suspected of causing genetic defects. Causes damage to eyes, blood

Obtain special instructions before use. Do not handle until all precautions have been and understood. Keep away from heat/sparks/open flames/hot surfaces.-No smoking. Use only in well-ventilated area. Do not breathe dust/fume/gas/mist/vapours/spray. Wash hands/skin thoroughly after handling. Do not eat, drink or smoke when using this product. Wear protective gloves/protective clothing/eye protection/face protection. Keep container tightly closed, locked up in well ventilated-area and cool. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Take off contaminated clothing and wash before reuse. In case of fire: Use dry sand, dry chemical or alcohol-resistant foam to extinguish. IF SWALLOWED: Immediatley call a POISON CENTER or doctor/physician. Rinse mouth. Do not induce vomiting. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Wash skin with soap/water/shower. Wash contaminated clothing before reuse. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician. If exposed: Call a POISON CENTÉR or doctor/physician. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician. Dispose of contents/container to an approved waste disposal plant.

Hazards not otherwise covered by GHS: None

Section 3. Composition Information

Exposure Limits(A blank value indicates no information available) The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

STEL(mg/m3) PEL(mg/m3) CEIL(mg/m3) Component CAS# Concentration Range

1330-20-7 >50% Xvlene 651 00 434 00 Phenol 108-5-2 5.00 10-25%

Section 4. First Aid Measures

Eye Contact: Check for and remove contact lenses. Wash with large amounts of water for 15 minutes. Seek medical attention.

Skin Contact: Remove contaminated clothing and shoes. Wash the affected area with large with soap and water. Seek medical attention

Ingestion: Give two glasses of water to a conscious victim. Do not induce vomiting. Seek medical attention

Inhalation: Move person to fresh air. If neccessary give CPR; warning this could pose a risk of exposure to the rescue breather. Seek medical attention

The most important known symptoms and effects are described in section 2 and/or section 11.

Section 5. Fire Fighting Measures

Extinguishing Media .: Use Dry Chemical, Foam or carbon Dioxide

Special Fire and Explosion Remarks ..: N/A

Section 6. Accidental Release Measures

Spill Cleanup and Disposal Special ..: Eliminate all ignition sources. Take up spills with absorbent vermiculite

Spill Cleanup.: Take up spills with absorbant material and containerize for proper disposal. Use proper PPE as per section 8. Provide ventilation.

Section 7. Handling and Storage

Storage and Handling Special ..: N/A

Storage and handling .: Keep container tightly closed. Store in a cool, dry area and protect from physical damage

Section 8. Exposure Controls/Personal Protection

Personal Protective Equipment ..: Splash Goggles, Gloves, Synthetic Apron, Vapor Respirator

This information is provided as a guide but proper PPE can only be determined by the end user and their situation.

Engineering Controls .: Provide local exhaust ventilation to keep the airborne concentrations of vapors below their respective threshold limit values. Ensure that eyewash

stations and safety showers are local to the work-station.

Section 9. Physical and Chemical Properties

Appearence...... Colorless liquid Evaporation Rate..... N/A Water Soluable? Yes Odor...... Aromatic hydrocarbon Upper Flammability Limit (%).: N/A Volatile Percent: 100 Odor Threshhold: N/A Partition Coefficient n-octanol/water: N/A Lower Flammability Limit (%): N/A pH: N/A Specific Gravity (@20C) 0.87 Auto Ignition Temp. N/A Melting Point..... N/A Vapor Pressure (mm Hg)....... 9 Decomposition Temp...... N/A Boiling Point N/A Vapor Density (Air=1) 3.7 Viscosity N/A Flash Point (F) TCC...... N/A Relative Density N/A

Section 10. Stability and reactivity

Special Remarks on Stability ..: Stabel

Special Remarks on Reactivity ..: N/A

s2032-1

SAFETY DATA SHEET

Page: 2 of: 2

Section 11. Toxological Information

Routes of Entry.: Inhalation, Skin Absorption, Ingestion

Animal Toxicity .: Xylene: Acute Oral (LD50) 4300 mg/kg (Rabbit) Acute Dermal (LD50) 2000 mg/kg (Rabbit); Ethyl Benzene: N/A; Phenol: Acute Oral (LD50) 317 mg/kg (Rat) Acute Dermal (LD50)

850 mg/kg (Rabbit)

Human Toxic Effects .: Target Organs: Eyes, skin, respiratory system, central nervous system, liver, kidney

Potential Acute Health Effects ..: Hazardous in case of inhalation, eye contact, skin contact, ingestion

Potential Chronic Health Effects ..: Tumorgenic. Phenol: IARC Code 3

Section 12. Ecological Information

Ecological Information .: N/A

Section 13. Disposal Considerations

Waste Disposal.: Dispose of in accordance with local, state and federal laws.

Section 14. Transport Information

DOT Identification .: UN1307, Xylenes, 3, III

Section 15. Regulatory Information

State Regulations.: New York release reporting list: Xylene (Mixed), Phenol

Sara Section 311 Reporting

Component	CAS#	Acu	ıte	Chronic	Fire	Pressure	Reactive	SARA302	SARA313	CERCLA	RCRA
Xylene	1330-20-7	No	No	No	No	No	Yes	Yes	Yes	No	
Phenol	108-5-2	No	No	No	No	No	Yes	Yes	Yes	No	

Section 16. Other Information

Review Date: 3/14/2023 Reviewed by: Admin MSDS Group Id.: 174

Notice: This SDS applies only to the material as packaged. If the material is altered by any means it may pose risks not mentioned here.

It is the user's responcibility to develope proper methods of handling and personal protection based on the actual conditions of use.