

**Section 1. Product and Company Identification**

Item Number.: s2670-1  
 Common Name.: Acid Fuchsin 5% Aqueous  
 Intended Use : In Vitro Diagnostic use. Laboratory Use Only  
 IN CASE OF EMERGENCY, CONTACT: CHEMTREC (24HR) 800-424-9300

Manufacturer.: Poly Scientific R&D Corp.

70 Cleveland Ave  
 Bay Shore NY 11706

polyrnd@polyrnd.com

**Section 2. Hazard Identification**

315 Skin corrosion/irritation Cat 2  
 319 Serious eye damage/eye irritation Cat 2A  
 335 Specific target organ toxicity, single exposure; Respiratory tract irritation Cat 3

**Warning**

Causes skin irritation and serious eye irritation.  
 May cause respiratory irritation.

Wash hands/skin thoroughly after handling. Use only in well-ventilated area. In case of inadequate ventilation wear respiratory ventilation. Wear protective gloves/ eye protection/ face protection/protective clothing. IF ON SKIN: Wash with plenty of soap and water. If skin irritation occurs: Get medical advice/ attention. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Call a POISON CENTER or doctor/ physician if you feel unwell. If eye irritation persists: Get medical advice/ attention. Take off contaminated clothing and wash before reuse. Store locked up. Dispose of contents/container to an approved waste disposal plant.

Hazards not otherwise covered by GHS: None

**Section 3. Composition Information**

Exposure Limits(A blank value indicates no information available) The specific chemical identity and/or exact percentage (concentration) of composition has been withheld as a trade secret.

Component	CAS#	PEL(mg/m3)	STEL(mg/m3)	CEIL(mg/m3)	Concentration Range
Acid Fuchsin	3244-88-0				<5%

**Section 4. First Aid Measures**

Eye Contact : Check for and remove contact lenses. Wash with large amounts of water for 15 minutes. Seek medical attention.  
 Skin Contact : Remove contaminated clothing and shoes. Wash the affected area with large with soap and water. Seek medical attention  
 Ingestion : Give two glasses of water to a conscious victim. Do not induce vomiting. Seek medical attention  
 Inhalation : Move person to fresh air. If necessary give CPR; warning this could pose a risk of exposure to the rescue breather. Seek medical attention  
 The most important known symptoms and effects are described in section 2 and/or section 11.

**Section 5. Fire Fighting Measures**

Extinguishing Media.: Use extinguisher media  
 Special Fire and Explosion Remarks.: N/A

**Section 6. Accidental Release Measures**

Spill Cleanup and Disposal Special.: Take up spills with absorbent vermiculite  
 Spill Cleanup.: Take up spills with absorbant material and containerize for proper disposal. Use proper PPE as per section 8. Provide ventilation.

**Section 7. Handling and Storage**

Storage and Handling Special.: N/A  
 Storage and handling.: Keep container tightly closed. Store in a cool, dry area and protect from physical damage

**Section 8. Exposure Controls/Personal Protection**

Personal Protective Equipment.: Safety Glasses, Gloves, Apron  
 This information is provided as a guide but proper PPE can only be determined by the end user and their situation.  
 Engineering Controls.: Provide local exhaust ventilation to keep the airborne concentrations of vapors below their respective threshold limit values. Ensure that eyewash stations and safety showers are local to the work-station.

**Section 9. Physical and Chemical Properties**

Appearance.....: Colorless liquid	Evaporation Rate.....: N/A	Water Soluable?.....: Yes
Odor.....: N/A	Upper Flammability Limit (%): N/A	Volatile Percent.....: N/A
Odor Threshold.....: N/A	Lower Flammability Limit (%): N/A	Partition Coefficient.....: n-octanol/water: N/A
pH.....: N/A	Specific Gravity (@20C).....: N/A	Auto Ignition Temp.....: N/A
Melting Point.....: N/A	Vapor Pressure (mm Hg).....: N/A	Decomposition Temp.....: N/A
Boiling Point.....: N/A	Vapor Density (Air=1).....: N/A	Viscosity.....: N/A
Flash Point (F) TCC.....: N/A	Relative Density.....: N/A	

**Section 10. Stability and reactivity**

Special Remarks on Stability.: Stable

Special Remarks on Reactivity.: N/A

Water Reactive.: No

**Section 11. Toxicological Information**

Routes of Entry.: Inhalation, Skin absorbtion, Ingestion

Animal Toxicity.: Acid Fuchsin: No occupational exposure limits established by Osha, ACGIH or NIOSH. Material has caused cancer in test animals.

Human Toxic Effects .: None known

Potential Acute Health Effects .: Hazardous in case of eye,skin contact, inhalation,ingestion

Potential Chronic Health Effects ...: N/A

**Section 12. Ecological Information**

Ecological Information .: N/A

**Section 13. Disposal Considerations**

Waste Disposal.: Dispose of in accordance with local,state and federal laws.

**Section 14. Transport Information**

DOT Identification .: Non Hazardous

**Section 15. Regulatory Information**

State Regulations.: N/A

## Sara Section 311 Reporting

Component	CAS#	Acute	Chronic	Fire	Pressure	Reactive	SARA302	SARA313	CERCLA	RCRA
Acid Fuchsin	3244-88-0	No	No	No	No	No	No	No	No	No

**Section 16. Other Information**

Review Date : 3/15/2023

Reviewed by : Admin

MSDS Group Id.: 6

Notice: This SDS applies only to the material as packaged. If the material is altered by any means it may pose risks not mentioned here.

It is the user's responsibility to develop proper methods of handling and personal protection based on the actual conditions of use.

While this SDS is based on reliable technical data, Poly Scientific R&D Corp. assumes no responsibility for the completeness or accuracy of the information contained herein.